

APPENDIX E
ADJACENT PROPERTY INSPECTION

**TABLE E-1
ADJACENT PROPERTIES OBSERVATION TABLE
NAVY AND MARINE CORPS RESERVE CENTER
READING, PENNSYLVANIA**

DESCRIPTION	DATE	PHOTO ID AND DESCRIPTION
NORTH		
CURRENT CONDITIONS - Bordered to the north by residential properties along Margaret Street.	Sept. 2006	Visual Site Inspection.
EDR Report – No records on northern adjoining property.	Sept. 2006	EDR Report, 2006
EAST		
CURRENT CONDITIONS – Bordered to the east by residential properties including Brookline Manor Apartments.	Sept. 2006	Visual Site Inspection.
EDR Report – No records on eastern adjoining property.	Sept. 2006	EDR Report, 2006
SOUTH		
CURRENT CONDITIONS – Bordered to the immediate south by Pershing Blvd. and then by residential developments.	2006	Visual Site Inspection.
EDR Report – No records on southern adjacent property.	Sept. 2006	EDR Report, 2006
WEST		
CURRENT CONDITIONS – Bordered to the immediate west by Kenhorst Blvd. and then Pennsylvania State Police barracks property beyond that at 600 Kenhorst Blvd.	2006	Visual Site Inspection.
EDR Report – Leaking Underground Storage Tank (LUST) release reported 08/5/89. One 10,000-gallon gasoline aboveground storage tank installed in 1998.	Sept. 2006	EDR Report, 2006
CONCLUSION		
Based on current observations of aerial and ground photographic records, the properties adjacent to NMCRC Reading, Pennsylvania consist primarily of residential properties, with the exception of the Western Adjacent commercial property, the Pennsylvania State Police Barracks Troop L at 600 Kenhorst Blvd.		